



Worldwide repairs carried out with PolymerMetal®

REP-# 063



Reconstruction of the sealing surface of the cover at a turbine. The repair was carried out with Ceramium, liquid and Hardener CE at an electric generating station.

MultiMetal
the MetalExistenceCompany®